

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Yates Petroleum Corporation	Contact Robert Asher
Address 104 S. 4 <sup>th</sup> Street	Telephone No. 575-748-1471
Facility Name Kiwi AKX State #8	Facility Type Battery

Surface Owner State	Mineral Owner State	API No. 30-025-31889
------------------------	------------------------	-------------------------

### LOCATION OF RELEASE

Unit Letter F	Section 16	Township 22S	Range 32E	Feet from the 1980	North/South Line North	Feet from the 2310	East/West Line West	County Lea
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude 32.39337 Longitude 103.68028

### NATURE OF RELEASE

Type of Release Crude Oil & Produced Water	Volume of Release 2 B/O & 10 B/PW	Volume Recovered 0 B/O & 8 B/PW
Source of Release Gun Barrel Fill Line	Date and Hour of Occurrence 6/28/2015; AM	Date and Hour of Discovery 6/28/2015; AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Fill line going to the gun barrel failed, causing the release. Vacuum truck(s) were called.



Describe Area Affected and Cleanup Action Taken.\*

An approximate area of 20' x 20' within the bermed battery. Shut off manual valves. A vacuum truck recovered no crude oil and 80% of the released produced water. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial analytical results for TPH & BTEX are under RRAL's a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results are above the RRAL's a work plan will be submitted to the OCD. **Depth to Ground Water: >100' (approximately 300', per the ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

**RECEIVED**

**By OCD District 1 at 1:04 pm, Jul 15, 2015**

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Robert Asher	Approved by Environmental Specialist: 	
Title: NM Environmental Regulatory Supervisor	Approval Date: <u>07/15/2015</u>	Expiration Date: <u>10/15/2015</u>
E-mail Address: boba@yatespetroleum.com	Conditions of Approval: 2RP- Discrete site samples required. Delineate and remediate per NMOCD guidelines. Geotagged photos of remediation required.	Attached <input type="checkbox"/> ogrid 25575 1RP-3732
Date: July 14, 2015 Phone: 575-748-4217		

\* Attach Additional Sheets If Necessary

nJXK1519647154

pJXK1519647450