

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Chancey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(432) 685-5824
Facility Name	Covington A Federal #9 CTB	Facility Type	Battery
Surface Owner	BLM	Mineral Owner	
		API No.	30-25-32036

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
SW ¼	25	22S	32E					Lea County, NM

Latitude N 32.35653° Longitude W 103.63042°

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	25 bbls	Volume Recovered	20 bbls
Source of Release	Corrosion of 2" steel water discharge line	Date and Hour of Occurrence	05/20/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By OCD District 1 at 1:53 pm, Jul 15, 2015



Describe Cause of Problem and Remedial Action Taken.*

Corrosion of a 2" steel water discharge line caused 25 bbls of produced water to leak onto the ground. A vacuum truck recovered 20 bbls of produced water and the line was repaired or replaced.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 30' x 100' inside the containment on location. Remediation will be completed in accordance with a remediation plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Chancey Summers	Approved by Environmental Specialist: 		
Title: HES Lead	Approval Date: 7/15/2015	Expiration Date: 10/15/2015	
E-mail Address: Chancey_Summers@oxy.com	Conditions of Approval: Discrete site samples required. Delineate and remediate per NMOCD guides. Geotagged photos of remediation required. Ensure BLM concurrence/approval.		Attached <input type="checkbox"/> ogrid 16696 1RP-3733
Date: 7-13-15 Phone: (432) 685-5824			

* Attach Additional Sheets If Necessary

pJXK1519650336

nJXK1519650093