

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Peashooter 4 Federal #1H	Facility Type: Battery

Surface Owner: Federal	Mineral Owner:	API No. 30-025-40313
------------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter D	Section 4	Township 19S	Range 32E	Feet from the 380	North/South Line North	Feet from the 760	East/West Line West	County Lea
------------------	--------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	---------------

Latitude 32.6956902 Longitude -103.7774048

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 22 bbls	Volume Recovered: 20 bbls
Source of Release: Filter Pot	Date and Hour of Occurrence: 6/24/2015 12:18 pm	Date and Hour of Discovery: 6/24/2015 12:18 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By OCD District 1 at 8:04 am, Jul 20, 2015



Describe Cause of Problem and Remedial Action Taken.*

This release was caused by a 1/2 nipple and needle valve on a filter pot. Vacuum trucks were dispatched to recover all standing fluid.

Describe Area Affected and Cleanup Action Taken.*

This release occurred within a lined facility. All fluids were able to be recovered. Repairs were made, the facility cleaned and put back into service.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: 		
Title: Senior Environmental Coordinator	Approval Date: 7/20/2015	Expiration Date: ///	
E-mail Address: atrujillo@concho.com	Conditions of Approval: //		Attached <input type="checkbox"/>
Date: July 8, 2015	Ensure BLM concurrence/Approval		ogrid 229137 1RP 3739

* Attach Additional Sheets If Necessary

nJXK1520128433

pJXK1520128612



CONCHO

COG Operating LLC

PEASHOOTER 4 FEDERAL COM #1H

UNIT D, SEC. 4-T19S-R32E

380' FNL & 760' FWL

LEA CO., NM NMNM-111962

API #30-025-40313