

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

MIDistrict I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

Release Notification and Corrective Action

OPERATOR

<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company: Chevron USA Inc.	
Contact: Nick Hampton	
Address: 15 Smith Rd., Midland, TX, 79705	Telephone No.: Work: 575-704-3143 Cell: 985-502-2342
Facility Name: Vacuum Gloriaetta West Unit Battery	
Facility Type: Battery	

Surface Owner: N/A	Mineral Owner: State of New Mexico	API No.:
--------------------	------------------------------------	----------

LOCATION OF RELEASE

Unit Letter	B
Section	1
Township	18S
Range	34E
Feet from the	North/South Line
Feet from the	East/West Line
County	Lea

Latitude = 32.796051 Longitude = -103.514502

NATURE OF RELEASE

Type of Release: Vent	Volume of Release: 102 MCF	Volume Recovered: 0 MCF
Source of Release: Flare	Date and Hour of Occurrence: 07/10/2015 01:30 AM	Date and Hour of Discovery: 07/10/2015 01:30 AM
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	IF YES, To Whom?
By Whom?	Date and Hour:	IF YES, Volume Impacting the Watercourse:
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
If a Watercourse was Impacted, Describe Fully.*		

RECEIVED
By OCD District 1 at 1:22 pm, Jul 20, 2015

Describe Cause of Problem and Remedial Action Taken.*	Venting at the VGWU Battery due to the compressor going down on low suction. Operations troubleshot, repaired and restarted the compressor.
---	---

Describe Area Affected and Cleanup Action Taken.*	N/A
---	-----

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	
Printed Name:	Nick Hampton
Approved by Environmental Specialist:	

Title: HE Specialist	Approval Date: 7/20/2015	Expiration Date: ///
----------------------	--------------------------	----------------------

E-mail Address: cikh@chevron.com	Conditions of Approval: ///	Attached <input type="checkbox"/> IRP-3741
Date: 07/13/2015	Phone: 985-502-2342	

* Attach Additional Sheets If Necessary

p)XXK1520148292

n)XXK1520148154