

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077	
Facility Name: SL Deep Federal #3	Facility Type: Battery	
Surface Owner: Federal	Mineral Owner:	API No. 30-025-39441

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	30	19S	32E	990	North	1650	West	Lea

Latitude 32.6360207 Longitude -103.8087845

NATURE OF RELEASE

Type of Release: Oil and Water	Volume of Release: 1 bbl Oil ; 35 bbl PW	Volume Recovered: 0 bbl Oil ; 30 bbl PW
Source of Release: Flowline	Date and Hour of Occurrence: 6/30/2015 8:30 am	Date and Hour of Discovery: 6/30/2015 8:30 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kellie Jones – NMOCD / Jim Amos – BLM	
By Whom? Amanda Trujillo	Date and Hour: Wed 7/1/2015 5:29 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By OCD District 1 at 10:46 am, Jul 21, 2015



Describe Cause of Problem and Remedial Action Taken.*

This release was caused by the corrosion of a steel flowline within the battery area. Vacuum trucks were dispatched to recover all standing fluid.

Describe Area Affected and Cleanup Action Taken.*

This release occurred within the bermed area among the separation equipment. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: 	
Title: Senior Environmental Coordinator	Approval Date: 07/21/2015	Expiration Date: 9/21/2015
E-mail Address: atrujillo@concho.com	Conditions of Approval: Discrete site samples required. Delineate and remediate per NMOCD guidelines.	Attached <input type="checkbox"/> ogrid 229137 1RP 3743
Date: July 14, 2015 Phone: 575-748-6940	Geotagged photos required. Ensure BLM concurrence/approval	

* Attach Additional Sheets If Necessary

pJXK1520248528

nJXK1520238865