

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	EOG Resources Inc.	Contact	Zane Kurtz
Address	5509 Champions Drive, Midland, TX 79706	Telephone No.	(432) 686-3667
Facility Name	Dragon 36 State 502	Facility Type	Flowback line

Surface Owner	NMSLO	Mineral Owner	NMSLO	API No.	30-025-42501
---------------	-------	---------------	-------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	36	24S	33E	555	North	1145	East	Lea

Latitude 32.179760 Longitude -103.521006

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	150 BBLs	Volume Recovered	23 BBLs
Source of Release	Open Flowback line valve	Date and Hour of Occurrence	7/15/2015 Time unknown.	Date and Hour of Discovery	7/16/2015 at approximately 2:00 PM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	2:43 PM on 7/16/2015 to Kellie Jones with the NMOCD		
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By OCD District 1 at 7:51 am, Jul 22, 2015

Describe Cause of Problem and Remedial Action Taken.*

A flowback line valve was opened anonymously causing flowback water to flow from site into pasture. . A vacuum truck was mobilized to the site to recover fluids.

Describe Area Affected and Cleanup Action Taken.*

Approximately 150 BBLs of produced water were released and 23 BBLs were recovered. The unrecovered barrels of produced water ran out into the pasture and were not recovered. Assessment and excavation of the soil in the area will take place in the near future.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Zu/Ku</i>	OIL CONSERVATION DIVISION		
Printed Name: <i>Zane Kurtz</i>	Approved by Environmental Specialist: <i>Jam Rhyer</i>		
Title: <i>EOG - Sr. Environmental Rep.</i>	Approval Date: <i>07/22/2015</i>	Expiration Date: <i>09/22/2015</i>	
E-mail Address: <i>ZANE_KURTZ@eogresources.com</i>	Conditions of Approval: Discrete site samples required. Delineate and remediate per NMOCD guides. Geotagged photos of remediation required.		Attached <input type="checkbox"/> ogrid 7377 IRP 3745
Date: <i>7-20-2015</i> Phone: <i>432 425 2023</i>			

* Attach Additional Sheets If Necessary

pJXK1520328505

nJXK1520328322