

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

This is an initial, not final.

☐ Initial Report ☒ Final Report

Name of Company: Chevron USA	Contact: Stephen Gwin	
Address: 2401 Avenue O Eunice, NM 88231	Telephone No.: 575-408-0073	
Facility Name: Monument 1 State 15	Facility Type: Oil Well	
Surface Owner: State of NM	Mineral Owner: State of NM	API No. 30-025-34167

LOCATION OF RELEASE

Unit Letter K	Section 1	Township 19S	Range 36E	Feet from the 1650	North/South Line South	Feet from the 2310	East/West Line West	County Lea
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude 32.686896 Longitude -103.308865

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 6.5 Bbls	Volume Recovered: 4 Bbls
Source of Release	Date and Hour of Occurrence: 7-9-2015 - 8:30 AM	Date and Hour of Discovery: 7-9-2015 - 8:30 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kellie Jones (575) 393-6161 x 111	
By Whom? Brian Criswell	Date and Hour: 7-10-2015 - 3:30 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By OCD District 1 at 8:44 am, Jul 22, 2015



Describe Cause of Problem and Remedial Action Taken.*

Spill was from stuffing box failure. A vacuum truck was called and picked up approximately 4 bbls of the produced water.

Describe Area Affected and Cleanup Action Taken.*

Vacuum truck picked up 4 Bbls of fluid.
Further remediation will be performed in accordance with a NMOCD approved remediation plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Stephen Gwin	Approved by Environmental Specialist: 		
Title: HES Specialist	Approval Date: 07/22/2015	Expiration Date: 09/22/2015	
E-mail Address: Stephen.gwin@chevron.com	Conditions of Approval: Discrete site samples required. Delineate and remediate per NMOCD guidelines. Geotagged photos of remediation required.		Attached <input type="checkbox"/> ogrid 4323 1RP 3746
Date: 7-21-2015	Phone: 575-408-0073		

* Attach Additional Sheets If Necessary

pJXK1520330116

nJXK1520329895