

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company OCCIDENTAL PERMIAN LTD.	Contact TONY AGUILAR	
Address ,	Telephone No. (575)397-8251	
Facility Name SOUTH HOBBS UNIT CTB	Facility Type OIL AND GAS PRODUCTION FACILITY	
Surface Owner OXY PERMIAN	Mineral Owner HOBBS (G-SA)	Lease No.

LOCATION OF RELEASE

Unit Letter A	Section 9	Township 19-S	Range 38-E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
------------------	--------------	------------------	---------------	---------------	------------------	---------------	----------------	---------------

Latitude 32.40'48.69" Longitude 103.08'52.64"

NATURE OF RELEASE

Type of Release Gas	Volume of Release 91.6 MCF	Volume Recovered 0
Source of Release NA	Date and Hour of Occurrence 7/2/2015 8:00:00 AM	Date and Hour of Discovery 7/2/2015 8:00:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? MAXEY BROWN	
By Whom? TONY AGUILAR	Date and Hour 7-2-2015 @ 7:30AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. NA	
If a Watercourse was Impacted, Describe Fully.* NA		

RECEIVED



By OCD District 1 at 8:24 am, Jul 27, 2015

Describe Cause of Problem and Remedial Action Taken.*

Cause:
FLARED AT THE SOUTH HOBBS UNIT CENTRAL TANK BATTERY (CTB). EUNICE DCP PLANT IS DOWN FOR REPAIRS. EOR
Remedial Action Taken:
DCP MADE REPAIRS AND RESTARTED PLANT AND FLARING STOPPED.

Describe Area Affected and Cleanup Action Taken.*
ALL GAS BURNED AT FLARE.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: TONY AGUILAR	Approved by District Supervisor: 	
Title: HES Specialist	Approval Date: 07/27/2015	Expiration Date: ///
E-mail Address: RAYMOND_AGUILAR@OXY.COM	Conditions of Approval: ///	
Date: 7-3-15 Phone: (575)397-8251	Attached <input type="checkbox"/> IRP 3751	

* Attach Additional Sheets If Necessary

nJXK1520830032

pJXK1520830177