

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company OXY Permian	Contact C.J. Summers
Address 1017 W STANOLIND RD	Telephone No. (575) 631-9436 CELL
Facility Name South Hobbs Unit CTB Battery	Facility Type

Surface Owner State	Mineral Owner	API No.
---------------------	---------------	---------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	06	19S	38E					Lea

Latitude 32.687736 Longitude -103.180427

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 300 BBLs	Volume Recovered Unknown
Source of Release Injection Trunk Line	Date and Hour of Occurrence 3/22/14	Date and Hour of Discovery 3/22/14
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Linda Reynolds (806)229-9549	
By Whom? Heath Haynes	Date and Hour 3/22/14 1:30 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.

RECEIVED

By OCD District 1 at 3:23 pm, Jul 28, 2015



Describe Cause of Problem and Remedial Action Taken.

Cause of leak is internal corrosion. Leak is outside of Header Building 5:

Describe Area Affected and Cleanup Action Taken.

SESI was contacted for assessment. Area will be delineated and an appropriate work plan submitted upon results.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Chancey Summers		Approved by Environmental Specialist: 	
Title: HES Advisor		Approval Date: 07/28/2015	Expiration Date: 09/28/2015
E-mail Address: Chancey_Summers@oxy.com		Conditions of Approval: Discrete site samples required. Delineate and remediate per NMOCD guidelines.	
Date: 3-27-14 Phone: (575)631-9436		Attached <input type="checkbox"/> 1RP 3769	

* Attach Additional Sheets If Necessary

Geotagged photos of remediation required.

pJXK1520955218

nJXK1520955061