

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Mewbourne Oil Company	Contact: Zack Thomas
Address: PO Box 5270 Hobbs NM 88241	Telephone No. 575-393-5905
Facility Name: Red Hills West SWD #1	Facility Type: Salt Water Disposal

Surface Owner: State	Mineral Owner: State	API No. 30-025-40162
----------------------	----------------------	----------------------

LOCATION OF RELEASE

Unit Letter P	Section 16	Township 26S	Range 32E	Feet from the 700'	North/South Line South	Feet from the 690'	East/West Line East	County Lea
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude 32.0375328 Longitude -103.6736145

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: estimated 1900 bbls PW	Volume Recovered: 1760 bbls PW
Source of Release: Tank Battery	Date and Hour of Occurrence 7-27-15	Date and Hour of Discovery 7-27-15 5:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kellie Jones (NMOCD) & Shelly Tucker (BLM) & Ian Dolly (SLO)	
By Whom? Zack Thomas	Date and Hour 7-29-15 8:00 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By OCD District 1 at 9:18 am, Jul 30, 2015



Describe Cause of Problem and Remedial Action Taken.*

Lightning struck fiberglass tank causing fire to destroy entire SWD storage facility. Jal VFD responded and extinguished the fire. All transfer pumps associated with this SWD were shut off.

Describe Area Affected and Cleanup Action Taken.*

Affected area- pad surface and approximately 300 yards East of pad. Vacuum trucks were used to recover all standing fluid.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Zack Thomas	Approved by Environmental Specialist: 	
Title: Environmental Rep.	Approval Date: 07/30/2015	Expiration Date: 09/30/2015
E-mail Address: zthomas@mewbourne.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 7-29-15 Phone: 575-602-2188	Discrete site sampels required. Delineate and remediate per NMOCD guidelines. Geotagged photos of remediation required. Ensure BLM concurrence/approval.	ogrid 14744

* Attach Additional Sheets If Necessary

pJXK1521133418

nJXK1521133280