

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Plains Marketing, LP	Contact	Camille Bryant
Address	2530 State Hwy. 214, Denver City, TX 79323	Telephone No.	(575) 441-1099
Facility Name	Lovington Station Tank 117275	Facility Type	Tank

Surface Owner	New Mexico State Land Office	Mineral Owner		Lease No.	
---------------	------------------------------	---------------	--	-----------	--

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	21	18S	36E					Lea

Latitude N 32.73427° Longitude W 103.35266°

#### NATURE OF RELEASE

Type of Release	Crude Oil	Volume of Release	101 bbls	Volume Recovered	66 bbls
Source of Release	Tank	Date and Hour of Occurrence	08/05/2015 @ 08:00	Date and Hour of Discovery	08/05/2015 @ 08:22
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Verbal notification to Kellie Jones		
By Whom?	Camille Bryant	Date and Hour	08/05/2015 @ 15:28		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*



**RECEIVED**

By OCD District 1 at 2:57 pm, Aug 07, 2015

Describe Cause of Problem and Remedial Action Taken.\* Internal corrosion caused a hole to develop in the floor of tank 117275 resulting in a release of crude oil.

Describe Area Affected and Cleanup Action Taken. The released crude oil impacted an area inside the secondary containment measuring approximately 40' X 80'. The impacted area will be remediated as per applicable NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>		
Printed Name: Camille Bryant	Approved by District Supervisor: 		
Title: Remediation Coordinator	Approval Date: 08/07/2015	Expiration Date: 10/07/2015	
E-mail Address: cjbryant@paalp.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 8/7/15	Site samples required. Delineate and remediate as per MNOCD guides. Geotag photographs of remediation required.		1RP-3791
Phone: (575) 441-1099			

\* Attach Additional Sheets If Necessary

nKJ1521954222

pKJ1521954545