

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED**

By OCD District 1 at 3:29 pm, Aug 28, 2015

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report ☐ Final Report

EOG Resources, Inc.	Contact Zane Kurtz
Address 5509 Champions Drive, Midland, TX 79706	Telephone No. 432-425-2023
Facility Name Vaca Ridge 30 Fed Com #1 poly line	Facility Type Salt Water Disposal water line

Surface Owner EOG	Mineral Owner EOG Resources	API No. 30-025-28873
-------------------	-----------------------------	----------------------

**LOCATION OF RELEASE**

Unit Letter G	Section 31	Township 24S	Range 34E	Feet from the 1471	North/South Line N	Feet from the 2184	East/West Line E	County Lea
------------------	---------------	-----------------	--------------	-----------------------	-----------------------	-----------------------	---------------------	---------------

Latitude 32.17727 Longitude -103.50748

**NATURE OF RELEASE**

Type of Release Produced Water	Volume of Release 40 bbls	Volume Recovered 15bbls
Source of Release: weak spot in flow line	Date and Hour of Occurrence 8/26/2015	Date and Hour of Discovery 8/26/2015
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.\*

**APPROVED**



By OCD District 1 at 3:29 pm, Aug 28, 2015

Describe Cause of Problem and Remedial Action Taken.\*

Weak spot in poly flow line caused release of 40bbls produce water alongside lease road. 15bbls recovered by vac truck upon discovery. 3<sup>rd</sup> party consultant will travel to site to delineate horizontal and vertical impacts. A work plan will be prepared to remediate impacted area. Work plan will include excavation of impacted material with direction to use poly liner prior to proper disposal at Sundance disposal in Eunice, NM. Clean backfill will be used once final clearance is granted.

Describe Area Affected and Cleanup Action Taken.\*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>		
Printed Name: Zane Kurtz, EOG Resources	Approved by Environmental Specialist: 		
Title: Sr. Environmental Rep.	Approval Date: 08/28/2015	Expiration Date: 10/28/2015	
E-mail Address: zane_kurtz@eogresources.com	Conditions of Approval: Discrete site samples required. Delineate and remediate per NMOCD guidelines.		Attached <input type="checkbox"/> 1RP 3825
Date: 8-27-2015 Phone: 432-425-2023	Geotagged photos of remediation required. Ensure BLM concurrence/approval.		pJXK1524055673 nJXK1524055566

\* Attach Additional Sheets If Necessary