

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Federal USA J #1	Facility Type: Battery

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-025-20367
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	30	19S	32E	990'	South	660'	East	Lea

Latitude 32.6269188 Longitude -103.799057

NATURE OF RELEASE

Type of Release: Oil & Produced Water	Volume of Release: 5 bbls Oil ; 85 bbls PW	Volume Recovered: 2 bbls Oil ; 35 bbls PW
Source of Release: Poly Flowline Leak	Date and Hour of Occurrence: 8/25/2015 2:00pm	Date and Hour of Discovery: 8/25/2015 2:00pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kellie Jones – NMOCD	
By Whom? Amanda Trujillo	Date and Hour: Thu 8/27/2015 5:16 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By OCD District 1 at 1:38 pm, Sep 16, 2015



Describe Cause of Problem and Remedial Action Taken.*

This release was caused by a poly flowline. Vacuum trucks were dispatched to recover all standing fluids and repairs were made to the flowline.

Describe Area Affected and Cleanup Action Taken.*

This release occurred in the pasture approximately 100' from the pad. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: 	
Title: Senior Environmental Coordinator	Approval Date: 09/16/2015	Expiration Date: 11/16/2015
E-mail Address: atrujillo@concho.com	Conditions of Approval: Discrete site samples required. Delineate and remediate per NMOCD guidelines. Geotagged photos of remediation required. Ensure BLM concurrence/approval.	Attached <input type="checkbox"/> IRP 3860
Date: September 18, 2015 Phone: 575-748-6940		

* Attach Additional Sheets If Necessary

nJXK1525948927

pJXK1525949020