

RECEIVED

By OCD District 1 at 10:39 am, Sep 17, 2015

INFORMATION ONLY



PANTHER ENERGY SERVICES, LLC

P.O. BOX 1321 JAL N.M. 88252 PHONE: 575-395-2654 FAX: 575-395-2162

Title

Date: 7-14-15

Company Name: Fulfer Oil + Cattle

Lease Name: South Langlie Jal Unit

Section: 25S

Township: ~~33S~~ 7

Range: 37E

OCD ID# - 3831

Work Plan

Make a one call on the contaminated area. Then come back and push up saturated top soil. Then use backhoe to trench sample and find clean. Take samples to lab for verification and then proceed with excavation and hauling off. After we are done excavating all contaminated soil we will then begin with backfilling.