

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED**

By Jamie at 3:20 pm, Sep 18, 2015

Form C-141

Revised August 6, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	BC Operating, Inc.	Contact	Pam Stevens
Address	P.O. Box 50820, Midland, Texas 79710	Telephone No.	432-684-9696
Facility Name	Government 'E' SWD #1	Facility Type	SWD

Surface Owner	BLM	Mineral Owner	BLM	API No.	30-025-23708
---------------	-----	---------------	-----	---------	--------------

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	25	19S	34E	600	South	1880	West	Lea

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

### NATURE OF RELEASE

Type of Release	Produced Salt Water & oil	Volume of Release	210 bbls	Volume Recovered	240 bbls
Source of Release	Lightening Strike	Date and Hour of Occurrence		Date and Hour of Discovery	6:00 a.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	on 08/21/15 Kelly Jones		
By Whom?	Bruce Madden	Date and Hour	8:20 a.m. on 08/21/15		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

**APPROVED**

By Jamie at 3:20 pm, Sep 18, 2015

Describe Cause of Problem and Remedial Action Taken.\*

Lightening hit a slop tank – Tank was cleared, demolished, site prepped and new tank which is up to BLM standards was moved in on 09/01/15. Operations continue.

Describe Area Affected and Cleanup Action Taken.\*

Inside firewall. Vacuum truck picked up 240 bbls. 171 BO & 39 BW & 30 bbls rainwater were picked up.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Pam Stevens</i>	<u>OIL CONSERVATION DIVISION</u>		
Printed Name: Pam Stevens	Approved by Environmental Specialist: <i>Jamie</i>		
Title: Regulatory Analyst	Approval Date: 09/18/2015	Expiration Date: ///	
E-mail Address: pstevens@bcoperating.com	Conditions of Approval: Ensure BLM concurrence/approval		Attached <input type="checkbox"/> IRP-3855
Date: 9/16/15	Phone: 432-684-9696		

\* Attach Additional Sheets If Necessary