

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.
RECEIVED
By JKeyes at 2:50 pm, Sep 18, 2015

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077	
Facility Name: Becknell State Com #1H	Facility Type: Battery	
Surface Owner: State	Mineral Owner:	API No. 30-025-41298

LOCATION OF RELEASE

Unit Letter I	Section 5	Township 21S	Range 33E	Feet from the 2450'	North/South Line South	Feet from the 660'	East/West Line East	County Lea
------------------	--------------	-----------------	--------------	------------------------	---------------------------	-----------------------	------------------------	---------------

Latitude 32.5073509 Longitude -103.5881882

NATURE OF RELEASE

Type of Release: Oil & Produced Water	Volume of Release: 3 bbls Oil ; 15 bbls PW	Volume Recovered: 2 bbls Oil ; 14 bbls PW
Source of Release: Tank Overflow	Date and Hour of Occurrence: 8/4/2015 6:00 PM	Date and Hour of Discovery: 8/4/2015 6:00 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

APPROVED

By JKeyes at 2:51 pm, Sep 18, 2015



Describe Cause of Problem and Remedial Action Taken.*

This release was caused by a tank overflow. Vacuum trucks were dispatched to recover all standing fluid.

Describe Area Affected and Cleanup Action Taken.*

This release occurred within a lined facility. All fluids were recovered, the facility cleaned and put back into service.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: 		
Title: Senior Environmental Coordinator	Approval Date: 09/18/2015	Expiration Date: ///	
E-mail Address: atrujillo@concho.com	Conditions of Approval: ///		Attached <input type="checkbox"/> IRP 3865
Date: August 18, 2015 Phone: 575-748-6940			

* Attach Additional Sheets If Necessary

nJXK1526153319

pJXK1526153391