

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

X Initial Report ☐ Final Report

Name of Company MACK ENERGY CORPORATION	Contact MATT BUCKLES
Address PO BOX 960 ARTESIA, NM 88211-0960	Telephone No. 575-748-1288
Facility Name Lea KG State TB	Facility Type TANK BATTERY

Surface Owner NMSLO	Mineral Owner MACK ENERGY CORP	API No. 30-025-39993
---------------------	--------------------------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	35	17S	33E	330	SOUTH	990	EAST	LEA

Latitude 32.784737 Longitude -103.627876

**NATURE OF RELEASE**

Type of Release PRODUCED WATER	Volume of Release 18BBLS	Volume Recovered 18BBLS
Source of Release PRODUCED WATER TANK	Date and Hour of Occurrence 10/8/15 3:00AM APROX.	Date and Hour of Discovery 10/8/15 6:10AM
Was Immediate Notice Given? <input type="checkbox"/> Yes X No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

**RECEIVED**

By JKeyes at 7:57 am, Oct 13, 2015



Describe Cause of Problem and Remedial Action Taken.\*

LIGHTNING STRIKE TO WATER TANK, PUMPER DROVE TO LOCATION AND SHUT DOWN WELL.

Describe Area Affected and Cleanup Action Taken.\*

BURNED FIBERGLASS TANK DOWN TO WATER LEVEL. MINIMAL SPILL WITHIN CONTAINMENT. NO DAMAGE TO CONTAINMENT LINER. PRODUCTION SHUT DOWN WITHIN THREE HOURS. ESTIMATED RELEASE OF 18 BBLS. WATER RECOVERED USING VACUUM TRUCK.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: MATT BUCKLES		Approved by Environmental Specialist: 	
Title: ENVIRONMENTAL		Approval Date: 10/13/2015	Expiration Date: 12/13/2015
E-mail Address: mattbuckles@mec.com		Conditions of Approval: Discrete site samples required. Delineate and remediate per NMOCD guidelines.	
Date: 10/9/2015	Phone: 575-748-1288	Attached <input type="checkbox"/> 1RP 3906	

\* Attach Additional Sheets If Necessary

Geotagged photos of remediation required.

pJXK1528628537

nJXK1528628444







