

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Linn Operating Inc.	Contact	E.L. Gonzales
Address	2130 W Bender Blvd Hobbs, NM 88240	Telephone No.	575-738-1739
Facility Name	Humphrey Queen Battery (HQU #10)	Facility Type	Battery
Surface Owner	Private	Mineral Owner	
		API No.	30-025-11424 Closest well

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	03	25S	37E	1650	North	1650	East	Lea

Latitude 32.1620255 Longitude -103.1475677

### NATURE OF RELEASE

Type of Release	NA	Volume of Release		Volume Recovered	
Source of Release		Date and Hour of Occurrence		Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			


**RECEIVED**  
By JKeyes at 12:26 pm, Oct 13, 2015

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
  
Linn has identified a historic structure at this location. Decommissioning to prevent misuse and hazards to general public. Further remediation efforts are will be addressed at site abandonment.

Describe Area Affected and Cleanup Action Taken.\*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:			
Printed Name:	E.L. Gonzales		
Title:	Production Supervisor	Approval Date:	10/13/2015
E-mail Address:	elgonzales@linenergy.com	Expiration Date:	12/13/2015
Date:	08/26/2015	Phone:	505-504-8002
		Conditions of Approval:	Attached <input type="checkbox"/>
		Discrete site samples required. Delineate and remediate per NMOCD guidelines.	1RP 3914
		Geotagged photos required.	

\* Attach Additional Sheets If Necessary

pJXK1528644705

nJXK1528644642