

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company	Marshall & Winston, Inc.	Contact	Todd Passmore
Address	P. O. Box 50880, Midland, TX 79710	Telephone No.	432-684-6373 or 432-894-0165
Facility Name	Klein 16 St. #2H	Facility Type	Well Location & Battery

Surface Owner	Alta Faye Klein c/o George L. Klein	Mineral Owner	State of New Mexico	API No.	30-025-40852
---------------	--	---------------	---------------------	---------	--------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	16	19S	35E	660	North	250	East	Lea

Latitude 32.665896 Longitude 103.454141

**NATURE OF RELEASE**

Type of Release	Oil & Water	Volume of Release	45 bbls	Volume Recovered	40 bbls
Source of Release	Heater Treater	Date and Hour of Occurrence		Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	08/12/15	08/12/15	2PM
By Whom?	Travis Flemmons	Ian Dolly			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Date and Hour	08/12/15 3:30 PM		
		If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

**RECEIVED**

By Kellie Jones at 10:40 am, Oct 13, 2015

Describe Cause of Problem and Remedial Action Taken.\*

Blown Gasket in the fire tube in the heater treater.  
Pick up all free standing fluid with vac. truck.



**APPROVED**

By Kellie Jones at 10:40 am, Oct 13, 2015

Describe Area Affected and Cleanup Action Taken.\*

Caliche around heater treater on well location.  
See attachments for corrective action taken.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Todd Passmore		Approved by Environmental Specialist: 	
Title: Operations Manager		Approval Date: 10/13/2015	Expiration Date: //
E-mail Address: tpassmore@mar-win.com		Conditions of Approval: //	
Date: 10/06/2015 Phone: 432-684-6373		Attached <input type="checkbox"/> 1RP-3800	

\* Attach Additional Sheets If Necessary