

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Linn Operating Inc.	Contact	E.L. Gonzales
Address	2130 W Bender Blvd Hobbs, NM 88240	Telephone No.	575-738-1739
Facility Name	CMU #5	Facility Type	Injection
Surface Owner	State	Mineral Owner	API No. 30-025-01440

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	17	17S	33E	660	North	1980	East	LEA

Latitude 32.8400612 Longitude -103.6832886

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	7bbls	Volume Recovered	0
Source of Release	FG Pipeline	Date and Hour of Occurrence	10/09/2015	Date and Hour of Discovery	10/09/2015 9:00am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

RECEIVED



By Kellie Jones at 10:49 am, Oct 13, 2015

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* At approx. 9am had an inj leak between CMU #5 and CMU #6. Upon arrival water was blowing out of the ground towards the southwest. Got line shut off and dug out and found a hole had come in the line.

Describe Area Affected and Cleanup Action Taken.* Water sprayed out in pasture about 480' at longest point and 120' at widest point.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:			
Printed Name:	E.L. Gonzales	Approved by Environmental Specialist: 	
Title:	Production Supervisor	Approval Date:	10/13/2015
E-mail Address:	elgonzales@linenergy.com	Expiration Date:	12/13/2015
Date:	10/12/2015	Phone:	505-504-8002
		Conditions of Approval:	Attached <input type="checkbox"/>
		Site samples required. Delineate and remediate as per MNOCD guides. Geotag photographs of remediation required.	1RP-3912

* Attach Additional Sheets If Necessary

nKJ1528639231
pKJ1528639458





