

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company Cimorex Energy	Contact Christine Alderman
Address 600 N Marienfeld Ste 600 Midland TX	Telephone No. 432-853-7059
Facility Name Maduro Unit 8	Facility Type production

Surface Owner BLM	Mineral Owner	API No. 30-025-38240
-------------------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	28	19S	33E	1740	S	660	W	Lea

Latitude 32.6103859 Longitude -103.2335129

NATURE OF RELEASE

Type of Release condensate	Volume of Release 60 bbls	Volume Recovered 59 bbls
Source of Release tank	Date and Hour of Occurrence 7/19/2015	Date and Hour of Discovery 7/19/2015
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kellie Jones	
By Whom? Christine Alderman	Date and Hour 7/23/2015 10am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


RECEIVED

By Kellie Jones at 3:57 pm, Oct 13, 2015

Describe Cause of Problem and Remedial Action Taken.*
Corrosion in the base of a 300 bbl steel oil tank

Describe Area Affected and Cleanup Action Taken.*
All fluids were released into a lined containment and were recovered.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Christine Alderman	OIL CONSERVATION DIVISION	
Printed Name: Christine Alderman	Approved by Environmental Specialist: 	
Title: ESH Supervisor	Approval Date: 10/13/2015	Expiration Date: 12/13/2015
E-mail Address: calderman@cimorex.com	Conditions of Approval: Site samples required. Delineate and remediate as per MNOCD guides. Geotag photographs of remediation required.	Attached <input type="checkbox"/> 1RP-3916
Date: 7/23/2015	Phone: 432-853-7059	

* Attach Additional Sheets If Necessary