

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: EOG Resources, Inc.	Contact: Zane Kurtz
Address: 5509 Champions Dr., Midland, TX 79705	Telephone No.: 432-425-2023
Facility Name: Endurance 25 Fed #2 SWD	Facility Type: Salt Water Disposal

Surface Owner: U.S. (BLM)	Mineral Owner: U.S (BLM)	API No. 30-025-41067
---------------------------	--------------------------	----------------------

LOCATION OF RELEASE

Unit Letter D	Section 25	Township 26S	Range 33E	Feet from the 2310	North/South Line North	Feet from the 990	East/West Line West	County Lea
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	---------------

Latitude 32.0153° Longitude -103.5315°

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 100 bbl	Volume Recovered: 40 bbl
Source of Release: Load Line Valve	Date and Hour of Occurrence: 10-04-2015/12:00 hrs	Date and Hour of Discovery: 10-05-2015/02:00hrs
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		



RECEIVED

By Kellie Jones at 9:58 am, Oct 16, 2015

Describe Cause of Problem and Remedial Action Taken. *Driver for Kent Trucking forgot to close valve at load line prior to pulling truck away causing produced water to spill on ground and migrate off location into pasture. Valve was closed and liquid picked up with vacuum truck.

Describe Area Affected and Cleanup Action Taken. *Spill occurred at load line and flowed south off location into pasture about 350 feet. Spill width is about 50 feet. Samples will be collected to delineate TPH and chloride in soil for remediation plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Jamon Hohensee, EOG Resources, Inc.	Approved by Environmental Specialist: 	
Title: Environmental Rep.	Approval Date: 10/16/2015	Expiration Date: 12/16/2015
E-mail Address: jamon_hohensee@eogresources.com	Conditions of Approval: Site samples required. Delineate and remediate as per MNOCD guides. Geotag photographs of remediation required.	Attached <input type="checkbox"/> 1 RP-3921
Date: 10-16-2015	Phone: 432-556-8074	

* Attach Additional Sheets If Necessary

nKJ1528936186
pKJ1528936421