

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Linn Operating Inc.	Contact	E.L. Gonzales
Address	2130 W Bender Blvd Hobbs, NM 88240	Telephone No.	575-738-1739
Facility Name	CMU B #35 Truck Spill	Facility Type	Injection
Surface Owner	Federal	Mineral Owner	API No. 30-025-00665

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	24	17S	32E	660	North	1980	East	Lea

Latitude 32.8254471 Longitude -103.7177887

NATURE OF RELEASE

Type of Release	Produced Water / BS	Volume of Release	50 bbls / 10bbls	Volume Recovered	0 / 0
Source of Release	Vac Truck unloaded on to ground	Date and Hour of Occurrence	10/14/2015	Date and Hour of Discovery	10/14/2015 1:00pm
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			



If a Watercourse was Impacted, Describe Fully.*

RECEIVED
By JKeyes at 7:37 am, Oct 21, 2015

Describe Cause of Problem and Remedial Action Taken.* At approximately 1 pm I was eastbound on Mescalero when I noticed produced water running off to the highway. I then pulled up to where I found where the spill had started. I then realized that the spill was caused by a Vac Truck that had illegally unloaded a load on to the ground.

Describe Area Affected and Cleanup Action Taken.* The spill ran south of the CMU 35 approximately 300 Ft. about 50-80 barrels of fluid was spilt. Sheriffs were notified.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: E.L. Gonzales	Approved by Environmental Specialist: 		
Title: Production Supervisor	Approval Date: 10/21/2015	Expiration Date: 12/21/2015	
E-mail Address: elgonzales@linenergy.com	Conditions of Approval: Discrete site samples required. Delineate and remediate per NMOCD guidelines.		Attached <input type="checkbox"/> 1RP 3932
Date: 10/20/2015	Phone: 505-504-8002		

* Attach Additional Sheets If Necessary

Geotagged photos of remediation required.

nJXK1529427257
pJXK1529427353