

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☒ Final Report

Name of Company: Chevron USA Inc.	Contact: Nick Hampton	
Address: 15 Smith Rd., Midland, TX, 79705	Telephone No.: Work: 575-704-3143 Cell: 985-502-2342	
Facility Name: The Fristoe C.C. & B&B Battery	Facility Type: Battery	
Surface Owner: El Paso Natural Gas	Mineral Owner: Federal Lands (QLS-086388 – USA NMNM-14218 LSE)	API No.

### LOCATION OF RELEASE

Unit Letter NW ¼ of NE ¼	Section 35	Township 24-S	Range 37E	Feet from the	North/South Line	Feet from the	East/West Line	County
--------------------------------	---------------	------------------	--------------	---------------	------------------	---------------	----------------	--------

Latitude: 32 deg 10.65 minutes north / Longitude: -103 deg 7.715 minutes west

### NATURE OF RELEASE

Type of Release: Flare	Volume of Release: 112 MCF	Volume Recovered: 0 MCF
Source of Release: Flare	Date and Hour of Occurrence 10/20/15 5:15 PM	Date and Hour of Discovery 10/20/15 5:15PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

N/A

**RECEIVED**  
**By JKeyes at 9:15 am, Oct 22, 2015**

Describe Cause of Problem and Remedial Action Taken.\*

Flaring due to 3<sup>rd</sup> Party Gas Plant (Targa) Shut-In. Chevron will keep in close contact with Targa to ensure that flaring is stopped soon as they are able to receive our gas.

Describe Area Affected and Cleanup Action Taken.\*

N/A

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

### OIL CONSERVATION DIVISION

Signature: Nick Hampton

Printed Name: Nick Hampton

Title: HE Specialist

E-mail Address: cikb@chevron.com

Date: 10/21/15

Phone: 985-502-2342

Approved by Environmental Specialist:

*Jani Keyes*

Approval Date: 10/22/2015

Expiration Date: ///

Conditions of Approval:

///

Attached ☐

IRP 3934

\* Attach Additional Sheets If Necessary

pJXK1529533246

nJXK1529533188