

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 10:28 am, Nov 02, 2015

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: ConocoPhillips	Contact: Spencer Cluff	
Address: 29 Vacuum Complex Lane	Telephone No. 575-746-7248	
Facility Name: EVGSAU 3202-11	Facility Type: Well	
Surface Owner: NMOCD	Mineral Owner: NMOCD	API No. 30-025-26652

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	32	17S	35E	2600	South	200	East	LEA

Latitude 32.7912865 Longitude -103.4719238 NAD83

NATURE OF RELEASE

Type of Release: Spill	Volume of Release: 477 BBLS	Volume Recovered: 475 BBLS
Source of Release: Trunk line	Date and Hour of Occurrence 10/30/2015 10:58 am	Date and Hour of Discovery 10/30/2015 11:03 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jamie Keyes	
By Whom? Spencer Cluff	Date and Hour: 11/02/2015 10:10 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

On October 30, 2015 at 1058 hrs. MDT, a line strike occurred on the trunk line from EVGSAU Satellite #3 to the EVGSAU CTB near the EVGSAU 3202-11 well that resulted in a release of 54 bbls oil and 423 bbls produced water, with 53 bbls oil and 422 bbls produced water recovered. The immediate action was to shut in EVGSAU Satellite #3 and to isolate the line. A work order has been submitted to repair the line and to remediate the area. The area will be remediated according to NMOCD and COPC guidelines.

Describe Area Affected and Cleanup Action Taken.*

The immediate action was to shut in EVGSAU Satellite #3 and to isolate the line. A work order has been submitted to repair the line and to remediate the area. The area will be remediated according to NMOCD and COPC guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Spencer A. Cluff</i>		OIL CONSERVATION DIVISION	
Printed Name: Spencer A. Cluff		Approved by Environmental Specialist: <i>Jamie Keyes</i>	
Title: LEAD HSE		Approval Date: 11/02/2015	Expiration Date: 01/02/2016
E-mail Address: spencer.a.cluff@conocophillips.com		Conditions of Approval: Discrete site samples required. Delineate and remediate per NMOCD guidelines. Geotagged photos of remediation required.	Attached <input type="checkbox"/> 1RP-3951
Date: 11/02/2015		Phone: 575-746-7248	

* Attach Additional Sheets If Necessary

nJXK1530637430
pJXK1530637584