

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 8:23 am, Nov 04, 2015

Form C-141

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077	
Facility Name: BATTLE AXE FEDERAL COM #002H	Facility Type: Battery	
Surface Owner: Federal	Mineral Owner: Federal	API No. 30-025-41370

LOCATION OF RELEASE

Unit Letter E	Section 2	Township 26S	Range 33E	Feet from the 2260'	North/South Line North	Feet from the 380'	East/West Line West	County Lea
------------------	--------------	-----------------	--------------	------------------------	---------------------------	-----------------------	------------------------	---------------

Latitude 32.0735359 Longitude -103.5503693

NATURE OF RELEASE

Type of Release: Oil & Produced Water	Volume of Release: 10 bbls Oil ; 62 bbls PW	Volume Recovered: 10 bbls Oil ; 62 bbls PW
Source of Release: Tank Overflow	Date and Hour of Occurrence: 10-3-2015 10:00 am	Date and Hour of Discovery: 10-3-2015 10:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kellie Jones – NMOCD	
By Whom? Lupe Carrasco	Date and Hour: Sat 10/3/2015 8:52 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

This release was caused by a tank overflow. Vacuum trucks were dispatched to recover all standing fluid.

Describe Area Affected and Cleanup Action Taken.*

This release remained within the bermed facility however the containment was unlined. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: 	
Title: Senior Environmental Coordinator	Approval Date: 11/04/2015	Expiration Date: 01/04/2016
E-mail Address: atrujillo@concho.com	Conditions of Approval: Discrete site samples required. Delineate and remediate per NMOCD guidelines.	Attached <input type="checkbox"/> IRP 3953
Date: October 17, 2015 Phone: 575-748-6940	Geotagged photos of remediation required.	

* Attach Additional Sheets If Necessary

nJXK1530830092
pJXK1530830161