

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
By JKeyes at 3:27 pm, Nov 05, 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Globe Energy Services	Contact: Tommy Morris	
Address: 113 Texas Ave. Eunice, NM 88231	Telephone No.: (325) 207-7775	
Facility Name: Eunice Fluid Services	Facility Type: Fluid Hauling	
Surface Owner: Chevron USA Inc.	Mineral Owner	API No.

LOCATION OF RELEASE

Unit Letter I	Section 34	Township 21S	Range 37E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
-------------------------	----------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	----------------------

Latitude 32.43356300 Longitude -103.14468400

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: Unknown	Volume Recovered: None
Source of Release: Frac Tanks	Date and Hour of Occurrence: Unknown	Date and Hour of Discovery: October 26th, 2015
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jamie Keyes	
By Whom? Tommy Morris	Date and Hour: October 26th, 2015	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Release of produced water from frac tanks that were being stored on the south side of the Globe yard in Eunice New Mexico. The fluids migrated offsite onto the adjacent property. Tetra Tech will sample the areas of concern to evaluate to the subsurface soils and present a remediation plan to the NMOCD prior to any significant remediation work.		
Describe Area Affected and Cleanup Action Taken.* The area of concern affected is South of Globe Energy's property line; outside the fence		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Tommy Morris	Approved by Environmental Specialist: 	
Title: HSE Director	Approval Date: 11/05/2015	Expiration Date: 01/06/2015
E-mail Address: tommy.morris@gesllc.com	Conditions of Approval: Discrete site samples required. Delineate and remediate per NMOCD guidelines.	Attached <input type="checkbox"/> 1RP 3960
Date: 11-5-15	Phone: 325-207-7775	Geotagged photos of remediation required.

* Attach Additional Sheets If Necessary

nJXK1530955218
pJXK1530955355