

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

C & J Energy Services	Freeman Young
Address P.O.Box 5208 Hobbs, New Mexico 88240	575-392-2578
State AB SWD #1	Commercial Salt Water Disposal

Surface Owner State of New Mexico	Mineral Owner State of New	30-025-23786
-----------------------------------	----------------------------	--------------

LOCATION OF RELEASE

C	03	19S		660	North Line	1980	South Line	Lea
---	----	-----	--	-----	------------	------	------------	-----

Latitude 32.6947220

Longitude -103.2402780

NATURE OF RELEASE

Disposal Fluids	65bbls	60 bbls
	8-10-2015 11:20 pm	8-10-15 11:25 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes	If YES, To Whom? Kellie Jones Environmental Specialist	
By Whom? Freeman Young	Date and Hour 8-11-2015 10:00 AM	
Was a Watercourse Reached? <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

The fluid was contained inside the dike area with a 60 mil plastic liner underneath the tanks, and up and down the walls of the dike.

Describe Cause of Problem and Remedial Action Taken.*

Lightning struck tanks at SWD causing a fire. The fire burned tanks down to fluid levels before it was extinguished. Free fluids were contained inside dike area and was recovered by vacuum trucks as soon as it was safe to do so.



RECEIVED

By Kellie Jones at 11:12 am, Nov 09, 2015

Describe Area Affected and Cleanup Action Taken.*

4 fiberglass unload tanks were destroyed as well as some electrical wiring on the West side of the facility. Fire Department contained fire to the West side by using foam and fresh water. Most all fluids were recovered, tanks were cut up and the waste materials were hauled to R360 waste disposal facilities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Dan Sewell	Approved by Environmental Specialist: 	
Title: Project Manager	Approval Date: 11/09/2015	Expiration Date: 01/09/2016
E-mail Address: Danny.Sewell@cjes.com	Conditions of Approval:	
Date: 10-28-15 9304	Site samples required. Delineate and remediate as per MNOCD guides. Geotag photographs of remediation required.	Attached <input type="checkbox"/> 1RP-3961
Phone: 325-450-		

* Attach Additional Sheets If Necessary

nKJ1531340624
pKJ1531340765