

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 8:34 am, Nov 10, 2015

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077	
Facility Name: CABO BLANCO STATE #001H	Facility Type: Battery	
Surface Owner: State	Mineral Owner: State	API No. 30-025-40702

LOCATION OF RELEASE

Unit Letter B	Section 5	Township 24S	Range 33E	Feet from the 330'	North/South Line North	Feet from the 2290'	East/West Line East	County Lea
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	------------------------	------------------------	---------------

Latitude 32.2530785 Longitude -103.5931778

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 47 bbls Oil	Volume Recovered: 46 bbls Oil
Source of Release: Tank overflow	Date and Hour of Occurrence: 10/5/2015 7:10 pm	Date and Hour of Discovery: 10/5/2015 7:10 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Tue 10/6/2015 10:18 AM	
By Whom? Lupe Carrasco	Date and Hour: Tue 10/6/2015 10:18 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

APPROVED

By JKeyes at 8:34 am, Nov 10, 2015



Describe Cause of Problem and Remedial Action Taken.*

This release was caused by a tank overflow. Vacuum trucks were dispatched to recover all standing fluid.

Describe Area Affected and Cleanup Action Taken.*

This release was contained within the lined containment. All fluid was able to be recovered. The facility was cleaned and put back into service.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Amanda Trujillo Davis	Approved by Environmental Specialist: 		
Title: Senior Environmental Coordinator	Approval Date: 11/10/2015	Expiration Date: ///	
E-mail Address: atrujillo@concho.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: October 19, 2015 Phone: 575-748-6940	///		1RP 3968

* Attach Additional Sheets If Necessary