District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410	Oil Conservation Division	By JKeyes at 10:24 am, Nov 10, 2015		
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	1220 South St. Francis Dr. Santa Fe, NM 87505 Ase Notification and Corrective Ac	tion		
Kett	OPERATOR	Initial Report	Final Report	

(

Name of Company: Chevron U.S.A. INC	Contact: Nick Ha	mpton		
Address: 15 Smith Rd, Midland, TX 79705	Telephone No.: 9	85-502-2342		
Facility Name: Buckeye CO2 Plant	Facility Type: Ga	Facility Type: Gas Processing Plant		
Surface Owner: State of New Mexico	Mineral Owner: N/A	API No. (closet well CVU 189 = 30-025-3334)		

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
Р	36	17S	34E					Lea

Latitude_<u>32° 47'15.77"</u> Longitude <u>103° 30' 32.533"</u>

NATURE OF RELEASE

Type of Release Flare: Propane Comp Blowdown	Volume of Release: 279.4 MCF	Volume Re	ecovered: 0 MCF		
Source of Release Flare: Flaring at CO2 Plant	Date and Hour of Occurrence	Date and H	lour of Discovery		
-	11/04/2015 4:30 PM	11/04/2015	5 4:30 PM		
Was Immediate Notice Yes No Not Required	If YES, To Whom?				
By Whom?	Date and Hour				
Was a Watercourse Reached?	If YES, Volume Impacting the Wat	tercourse			
☐ Yes ⊠ No	in TEB, volume impacting the wa	lereouise.			
If a Watercourse was Impacted, Describe Fully.*					
N/A					
Describe Cause of Problem and Remedial Action Taken.*					
Flaring event due to Plant shutdown.					
Describe Area Affected and Cleanup Action Taken.*					
N/A					
I hereby certify that the information given above is true and complete to	the best of my knowledge and understa	and that pursu	ant to NMOCD rules and		
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability					
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health					
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other					
federal, state, or local laws and/or regulations.		-			
	OIL CONSERV	VATION I	DIVISION		
Signature: Nick Hampton		1			
	Approved by Environmental Specialis	Jank!	hye		
Printed Name: Nick Hampton	Approved by Environmental Specialis	St. 7	, 		
	11/10/2015 ///				
Title: HE Specialist	Approval Date:	Expiration D	vate:		
E-mail Address: cikb@chevron.com	Conditions of Approval:				
			Attached		
Date: 11/09/2015 Phone: 985-502-2342	///		1RP 3969		

* Attach Additional Sheets If Necessary