

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Mewbourne Oil Company	Contact: Zack Thomas	
Address: PO Box 5270 Hobbs NM 88241	Telephone No. 575-393-5905	
Facility Name: Antelope 9 B3PA State Com #1H	Facility Type: Producing Oil Well	
Surface Owner: State	Mineral Owner: State	API No. 30-025-42651

### LOCATION OF RELEASE

Unit Letter P	Section 9	Township 23S	Range 34E	Feet from the 185'	North/South Line South	Feet from the 750'	East/West Line East	County Lea
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude 32.3124202 Longitude -103.46889917

### NATURE OF RELEASE

Type of Release: Oil	Volume of Release: estimated 25 bbls	Volume Recovered: 20 bbls
Source of Release: Separator	Date and Hour of Occurrence 11-10-15	Date and Hour of Discovery 11-10-15 7:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kellie Jones	
By Whom? Zack Thomas	Date and Hour 11-10-15 1:15 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		

**RECEIVED**

By Kellie Jones at 9:38 am, Nov 12, 2015



Describe Cause of Problem and Remedial Action Taken.\*

Lost supply gas to dumps/motor valves causing separator to fill up/pressure up. Pressure relief valve popped off spraying fluid onto ground. Well was shut-in to stop release.

Describe Area Affected and Cleanup Action Taken.\*

Affected area- 100 ft by 100 ft area of pasture North of separation equipment. Vacuum trucks were used to recover all standing fluid.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Zack Thomas	Approved by Environmental Specialist: 	
Title: Environmental Rep.	Approval Date: 11/12/2015	Expiration Date: 01/12/2016
E-mail Address: zthomas@mewbourne.com	Conditions of Approval: Site samples required. Delineate and remediate as per MNOCD guides. Geotag photographs of remediation required.	Attached <input type="checkbox"/> 1RP-3976
Date: 11-11-15	Phone: 575-602-2188	

\* Attach Additional Sheets If Necessary

nKJ1531634840  
pKJ1531635030