

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011  
Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Dusty Wilson
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	432-685-5771
Facility Name	East Eumont Unit #35	Facility Type	Well location

Surface Owner	State	Mineral Owner		API No.	30-025-05591
---------------	-------	---------------	--	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	10	19S	37E					Lea

Latitude 32.6730292 Longitude 103.24139

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	100 bbls	Volume Recovered	95 bbls
Source of Release	Corrosion of the fitting on high pressure hose	Date and Hour of Occurrence	11/2/15	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Kelly Jones, Jamie Keyes		
By Whom?	Kathy Purvis @ BBC International	Date and Hour	11/2/15 3:25 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

**RECEIVED**

By Kellie Jones at 10:13 am, Nov 12, 2015


Describe Cause of Problem and Remedial Action Taken.\*

Corrosion of a fitting on a 1" high pressure rubber hose at the well head. A vacuum truck recovered 95 bbls of produced water and the fitting is being repaired.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 120' x 360' on location around the well head and off location. Remediation will be completed in accordance with the remediation plan approved by NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name: Dusty Wilson	Approved by Environmental Specialist: 		
Title: Environmental Advisor	Approval Date: 11/12/2015	Expiration Date: 01/12/2016	
E-mail Address: : Dusty.Wilson@oxy.com	Conditions of Approval: Site samples required. Delineate and remediate as per MNOCD guides. Geotag		Attached <input type="checkbox"/> 1RP-3977
Date: 11/11/15	Phone:		

\* Attach Additional Sheets If Necessary

photographs of remediation required.

nKJ1531636939  
pKJ1531637494