

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

Form C-141
By JKeyes at 8:25 am, Nov 19, 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Devon Energy Production Co LP (6137)	Contact: Jeff Heath, Devon Assist. Foreman
Address: PO Box 250 Artesia, NM 88211	Telephone No. 575- 513-2274
Facility Name: Arena Roja Fed Unit 15H - 16H Well Pad	Facility Type : 2-well pad location
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-025-42671, 42672	

LOCATION OF RELEASE

Unit Letter A	Section 28	Township 26S	Range 35E	Feet from the 184	North/South Line North	Feet from the 200	East/West Line East	County Lea
-------------------------	----------------------	------------------------	---------------------	-----------------------------	----------------------------------	-----------------------------	-------------------------------	----------------------

Latitude: **32.021029** Longitude: **-103.364480**

NATURE OF RELEASE

Type of Release: Treated Water	Volume of Release: 20 bbls	Volume Recovered: 15 bbls
Source of Release: The bladder on the minion tanks split.	Date and Hour of Occurrence 11/16/15; 4:00 AM	Date and Hour of Discovery 11/16/15; 4:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM-Jim Amos OCD-Kelly Jones	
By Whom? Jeff Heath	Date and Hour: 11/16/15; BLM-3:16 PM OCD-7:13 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.* **N/A**



Describe Cause of Problem and Remedial Action Taken.*

While prefilling minion tanks, a sudden inrush of air from the transfer lines caused the bladder to split on the minion tanks causing approximately 20 barrels treated water to spill on location pad. Treated water remaining in the minion tanks was transferred to frac tanks and vacuum truck put it back into the treated water pond. The treated water line was pigged back to the treated pond as well.

Describe Area Affected and Cleanup Action Taken.*

Approximately 15 barrels of treated water was recovered by vacuum truck. Devon has contacted an environmental company to delineate and develop a work plan after completions operations are finished and moved off of location.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Denise Menoud	Approved by Environmental Specialist: 	
Title: Field Admin Support	Approval Date: 11/19/2015	Expiration Date: 01/19/2016
E-mail Address: Denise.Menoud@dvn.com	Conditions of Approval: Discrete site samples required. Delineate and remediate per NMOCD guidelines.	
Date: 11/18/2015 Phone: 575-746-5544	Attached <input type="checkbox"/> 1RP 3984	

* Attach Additional Sheets If Necessary

Geotagged photos of remediation required.

Arena Roja Fed Unit 15H
Spill 20 bbls Treated Water



This map is for illustrative purposes only and is neither a legally recorded map nor survey and is not intended to be used as one. Devon makes no warranty, representation, or guarantee of any kind regarding this map.

WGS_1984_Web_Mercator_Auxiliary_Sphere
Prepared by: D Menoud
Map is current as of: 18-Nov-2015



Miles
0 0.01 0.02 0.04 1:1,779

NENE-28-26S-35E

NWNW-27-26S-35E

20 bbls treated water

FAHMS

Lat: 32.021029
Lon: -103.364480

Arena Roja Fed Unit 15H





