

RECEIVED**By JKeyes at 3:20 pm, Nov 24, 2015**

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action**OPERATOR**
☒ Initial Report ☐ Final Report



Name of Company	Key Energy Services, LLC	Contact	Bobby Sisson
Address	1301 McKinney Street, Suite 1800, Houston, TX 77010	Telephone No.	806-401-4349
Facility Name	Atha SWD	Facility Type	SWD
Surface Owner	Dasco & McCasland	Mineral Owner	Dasco & McCasland
		API No.	30-025-04861

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	31	21S	36E	660'	South Line	660'	West Line	Lea

Latitude 32° 42' 99.3" N Longitude 103° 31' 03.9' W

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	5 bbl	Volume Recovered	5 bbl
Source of Release	Vacuum truck	Date and Hour of Occurrence	11/09/2015 0500	Date and Hour of Discovery	11/09/2015 0500
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. n/a			
If a Watercourse was Impacted, Describe Fully.* Not applicable.					
Describe Cause of Problem and Remedial Action Taken.* While unloading a vacuum truck, it sprang a leak. The spill was 100% contained on the cement unload slab.					
Describe Area Affected and Cleanup Action Taken.* Not applicable					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: 		OIL CONSERVATION DIVISION			
Printed Name: Bobby J. Sisson		Approved by Environmental Specialist: 			
Title: Area Director		Approval Date: 11/24/2015		Expiration Date: 01/24/2016	
E-mail Address: bsisson@keyenergy.com		Conditions of Approval: Discrete sample required. Delineate and remediate per NMOCD guidelines.		Attached <input type="checkbox"/> 1RP 3997	
Date: 11-24-15		Phone: 806-237-3019			

* Attach Additional Sheets If Necessary