

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

X Initial Report ☐ Final Report

Name of Company XTO Energy Inc.	Contact John Robinson
Address 500 West Illinois, Suite 100 Midland, T. X. 79701	Telephone No. 575-441-5199
Facility Name Eunice Monument South Unit # 110	Facility Type Pumping Well
Surface Owner STATE	Mineral Owner
API No. 30-025-06284	

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	30	20S	37E	1980	north	660	west	lea

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

### NATURE OF RELEASE

Type of Release Produced fluid	Volume of Release 4.28 oil 81.40 wtr	Volume Recovered 3.75 oil 71.25 wtr
Source of Release Flow line	Date and Hour of Occurrence 11-24-15 8:00 pm	Date and Hour of Discovery 11-25-15 7:00 am
Was Immediate Notice Given? X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kelly Jones NM OCD	
By Whom? John Robinson	Date and Hour 11-25-15 9:00 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		

**RECEIVED**

By Kellie Jones at 9:55 am, Nov 30, 2015



#### Describe Cause of Problem and Remedial Action Taken.\*

Warn flow line. Cleaned up all fluid with vac truck and all saturated soil with a backhoe. Will clean up the rest of the contaminated soil when one call is ready.

#### Describe Area Affected and Cleanup Action Taken.\*

The leak stayed in the caliche road. Will test soil and clean up as per ocd regulations.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: John Robinson	Approved by Environmental Specialist: 	
Title: Maintenance Foreman	Approval Date: 11/30/2015	Expiration Date: 01/30/2016
E-mail Address: john_robinson@xtoenergy.com	Conditions of Approval: Site samples required. Delineate and remediate as per MNOCD guides. Geotag photographs of remediation recommended.	Attached <input type="checkbox"/> 1RP-4001
Date: 11-25-15	Phone: 575-441-5199	

\* Attach Additional Sheets If Necessary

nKJ1533436131  
pKJ1533436284