

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 8:03 am, Dec 10, 2015

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Chevron USA Inc.	Contact: Nick Hampton	
Address: 15 Smith Rd., Midland, TX, 79705	Telephone No.: Work: 575-704-3143 Cell: 985-502-2342	
Facility Name: West Dollarhide Drinkard Unit Battery	Facility Type: Injection Line	
Surface Owner: State surface	Mineral Owner: (QLS-091040 – State of New Mexico B-9613 LSE)	API No.

LOCATION OF RELEASE

Unit Letter D	Section 32	Township 24-S	Range 38E	Feet from the	North/South Line	Feet from the	East/West Line	County
------------------	---------------	------------------	--------------	---------------	------------------	---------------	----------------	--------

Latitude: 32 deg 9.788 minutes north / Longitude: -103 deg 5.218 minutes west

NATURE OF RELEASE

Type of Release: Spill	Volume of Release: 6.225 BBLS produced water	Volume Recovered: 0 BBLS produced water
Source of Release: WDDU South West Lateral Injection Line	Date and Hour of Occurrence 12/5/15 11:15 AM	Date and Hour of Discovery 12/5/15 11:15 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Leak in injection line from caused the release of 6.225 BBLS of produced water. All contaminated soil will be removed.		
Describe Area Affected and Cleanup Action Taken.* The area affected was a mixture of caliche, soil, and sand.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
OIL CONSERVATION DIVISION		
Signature: Nick Hampton	Approved by Environmental Specialist: <i>Jane Keyes</i>	
Printed Name: Nick Hampton		
Title: HE Specialist	Approval Date: 12/10/2015	Expiration Date: 02/10/2016
E-mail Address: cikb@chevron.com	Conditions of Approval:	
Date: 12/10/15 Phone: 985-502-2342	Discrete site samples required. Delineate and remediate per NMOCD guidelines. Geotagged photos recommended.	Attached <input type="checkbox"/> 1RP 4008

* Attach Additional Sheets If Necessary

nJXK1534428787
pJXK1534428902