

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 8:02 am, Dec 16, 2015

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Cimorex Energy	Contact Christine Alderman	
Address 600 N Marienfeld Ste 600 Midland TX	Telephone No. 432-853-7059	
Facility Name Hallertau Fed Com 5 #2h	Facility Type production	
Surface Owner BLM	Mineral Owner	API No. 30-025-40436

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	05	26S	32E	330	S	330	E	Lea

Latitude_32.06587_Longitude_-103.68969

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 100 bbls	Volume Recovered 60 bbls
Source of Release poly transfer line	Date and Hour of Occurrence 4/11/2015	Date and Hour of Discovery 4/11/2015
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Doc Oberding/Sol Hughes	
By Whom? Christine Alderman	Date and Hour 4/12/2015 8:30 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*
A poly water transfer line ruptured due to pressure.

Describe Area Affected and Cleanup Action Taken.*

The produced water remained on the lease road, the road was backdragged. Samples will be taken to determine cleanup.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:	Approved by Environmental Specialist: 	
Printed Name: Christine Alderman	Approval Date: 12/16/2015 Expiration Date: 02/16/2016	
Title: ESH Supervisor	Conditions of Approval: Discrete site samples required. Delineate and remediate per NMOCD guidelines. Geotagged photos of remediation recommended. Ensure BLM concurrence/approval.	
E-mail Address: calderman@cimorex.com	Attached <input type="checkbox"/> 1RP 4021 nJXXK1535028737 pJXXK1535028837	
Date: 4/14/2015 Phone: 432-853-7059		

* Attach Additional Sheets If Necessary