

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED**

By JKeyes at 2:02 pm, Dec 31, 2015

Form C-141

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company SUNDOWN ENERGY LP	Contact Jimmy Lewis
Address 16400 Dallas Parkway Ste 100 Dallas, TX 75248	Telephone No. 432-943-8770
Facility Name Bobbi State Waterflood Unit	Facility Type Tank Battery and SWD

Surface Owner	Mineral Owner	API No. (R-13731)
---------------	---------------	-------------------

### LOCATION OF RELEASE

Unit Letter N	Section 20	Township 18S	Range 36E	Feet from the 330	North/South Line SOUTH	Feet from the 2310	East/West Line WEST	County LEA
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

### NATURE OF RELEASE

Type of Release Salt Water	Volume of Release 150 bbls	Volume Recovered None
Source of Release Water Tank	Date and Hour of Occurrence 12/26/2015 11:00 pm	Date and Hour of Discovery 12/26/2015 11:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Maxey Brown, NM OCD	
By Whom? Wes Able	Date and Hour 12/28/2015 2:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

Water tank was struck by lightning, catching tank on fire. All oil on top of water was completely burned off. Clean up will begin as soon as equipment can get to the location. Location not accessible due to recent heavy snow & rain.

Describe Area Affected and Cleanup Action Taken.\*

The area inside the containment but also had some fluid escape the contained area. Amount unknown due to flooding. As soon as location is accessible, trucks will move in to recover any remaining fluid.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Jimmy Lewis		Approved by Environmental Specialist: 	
Title: Production Superintendent		Approval Date: 12/31/2015	Expiration Date: 03/01/2016
E-mail Address: jlewis@sundownenergy.com		Conditions of Approval: Discrete site samples required. Delineate and remediate per NMOCD guidelines.	
Date: 12/29/2015 Phone: 432-943-8770		Attached <input type="checkbox"/> IRP 4061	

\* Attach Additional Sheets If Necessary

Geotagged photos recommended. Ensure NM SLO concurrence/approval.

nJXK1536550370  
pJXK1536550459