<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mex RECEIVED Energy Minerals and Natura By JKeyes at 9:56 am, Jan 07, 2016

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

## **Release Notification and Corrective Action**

						OPERATOR							Report		
Name of Company: COG Operating LLC						Contact: Ro		•							
Address: 600 West Illinois Avenue, Midland TX 79701						Telephone No. 432-230-0077									
Facility Name: PINTAIL 3 FEDERAL #001H						Facility Type: Battery									
Surface Owner: Federal Mineral Owner:						:: API No. 30-025-40684									
				LOCA	TIO	N OF REI	FASE								
Unit Letter	Section	th/South Line   Feet from the   East/West Line   Country						itv							
Unit Letter Section Township Range Feet from the Nort O 03 26S 32E 260'						South 2290			East Lea			-			
	<b>Latitude</b> 32.0657692 <b>Longitude</b> - 103.6615829														
	NATURE OF RELEASE														
Type of Release: Produced Water						Volume of Release: Volume Recovered: 20 bbls PW 20 bbls PW									
Source of Release:						Date and Hour of Occurrence: Date and Hour of Discovery:									
Fittings/Connections						10/26/2015 1:00 pm 10/26/2015 1:00 pm									
Was Immedi	ate Notice G	If YES, To Whom?													
			Yes _	No Not R	equired										
By Whom? Was a Water	D1	Date and Hour:  If YES, Volume Impacting the Watercourse.													
was a water	course Reaci	11 1 E.S., volume impacting the watercourse.													
If a Watercon	irea was Imp	ancted Descr	iba Eully ?	- k											
ii a watercot	urse was mip	acteu, Descri	ibe runy.												
Describe Cause of Problem and Remedial Action Taken.*															
This release was caused by a corroded nipple on a water leg. Vacuum trucks were dispatched to recover all standing fluid.															
Describe Are	a Affected a	nd Cleanup A	Action Tak	ken.*											
- T															
This release	This release occurred within a lined facility. Repairs were made, the facility cleaned and put back into service.														
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and															
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability															
							on that pose a thre								
							e the operator of i	•				_			
federal, state	, or local law	s and/or regu	ılations.				_								
		OIL CONSERVATION DIVISION													
Signature:	56	-/-	ijil	Le.					2						
						Approved by Environmental Specialist: Jamkhyu									
Printed Name	e: Amanda			///											
Title: Senior Environmental Coordinator						Approval Date: 01/07/2016			Expiration Date:						
						•									
E-mail Address: atrujillo@concho.com						Conditions of Approval:			Attached						
Date: Nover	nber 9, 2015	Pho:	ne: 575-74	18-6940	III			1RP 4085							