

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Devon Energy Production Company	Contact	Randy Gladden, Production Foreman
Address	6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No.	575-513-9463
Facility Name	Bell Lake 24 Federal 1 H	Facility Type	Oil
Surface Owner	Federal	Mineral Owner	Federal
		API No	30-025-41182

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	24	24S	32E	200	South	660	West	Lea

Latitude: 32.196434 Longitude: 103.6347809

### NATURE OF RELEASE

Type of Release Spill	Oil	Volume of Release	10 BBLS	Volume Recovered	None
Source of Release	Three phase vessel	Date and Hour of Occurrence	01/04/2016 9:30am	Date and Hour of Discovery	01/04/2016 9:30am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	BLM- Jim Amos-voicemail OCD- Kellie Jones-Voicemail		
By Whom?	Santiago (Jim) Huerta	Date and Hour	BLM- 1/05/2016 @ 7:00am OCD- 1/05/2016 @ 7:10am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	N/A		

If a Watercourse was Impacted, Describe Fully.\* N/A


#### Describe Cause of Problem and Remedial Action Taken.\*

Due to the weather the man way cover flange froze causing the three phase production vessel separator to blow off and spray 10 BBLS of oil on location and into pasture. The three phase vessel was immediately bypassed to stop release.

#### Describe Area Affected and Cleanup Action Taken.\*

10 BBLS of oil was released affecting an area approximately 20ft x 50ft on the west side of the location. Approximately less than 4 BBLS of the released oil sprayed in a Westerly direction away from the pad into the pasture. 4 BBLS of released oil was recovered via vacuum truck. Environmental agency will be contacted for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Sarah Gallegos-Troublefield	OIL CONSERVATION DIVISION		
Printed Name: Sarah Gallegos-Troublefield	Approved by Environmental Specialist: 		
Title: Field Admin Support	Approval Date: 01/07/2016	Expiration Date: 03/07/2016	
E-mail Address: Sarah.Gallegos-Troublefield@dmv.com	Conditions of Approval: Site samples required. Delineate and remediate as per MNOCD guides. Geotag photographs of remediation recommended.		Attached <input type="checkbox"/> IRP-4080
Date: 1/06/2016	Phone: 575.748.1864		

\* Attach Additional Sheets If Necessary

nKJ1600727134  
pKJ1600727477