

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

|                 |   |               |                                    |
|-----------------|---|---------------|------------------------------------|
| Name of Company | Devon Energy Production Company         | Contact       | Rick Campos – Construction Foreman |
| Address         | 6488 Seven Rivers Hwy Artesia, NM 88210 | Telephone No. | 575-513-1933                       |
| Facility Name   | Gaucha Unit 6H                          | Facility Type | Gas Well                           |
| Surface Owner   | Federal                                 | Mineral Owner | Federal                            |
|                 |   | API No        | 3002534789                         |

### LOCATION OF RELEASE

|             |         |          |       |               |                  |               |                |        |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
| P           | 17      | 22S      | 34E   | 660           | S                | 660           | E              | Lea    |

Latitude: 32.3862562

Longitude: 103.4856777

### NATURE OF RELEASE

|                             |   |  |  |                            |                   |
|-----------------------------|---|--|--|----------------------------|-------------------|
| Type of Release             | Produced Water  | Volume of Release                        | 30 BBLs  | Volume Recovered           | 20 BBLs           |
| Source of Release           | Separator   | Date and Hour of Occurrence              | 1/22/2016 3:34 PM  | Date and Hour of Discovery | 1/22/2016 3:34 PM |
| Was Immediate Notice Given? | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom?                         | BLM: Jim Amos<br>OCD: Kellie Jones                               |                            |                   |
| By Whom?                    | Kelly Miller MBF Inspector  | Date and Hour                            | BLM: January 25, 2016 7:45 AMS<br>OCD: January 25, 2016 11:25 AM |                            |                   |
| Was a Watercourse Reached?  | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No                                       | If YES, Volume Impacting the Watercourse | N/A  |                            |                   |

If a Watercourse was Impacted, Describe Fully.\*

N/A

Describe Cause of Problem and Remedial Action Taken.\*

While repairing leak on separator clamp was turned to open position resulting in produced water release. Clamp was turned to closed position to prevent further release. New clamp and vertical ball valve were installed.

Describe Area Affected and Cleanup Action Taken.\*

Approximately 30 BBLs of produced water was released on the west side of the pad. Approximate size of the affected area 60'x80'. All released produced water remained on pad. 20 BBLs produced water was recovered by Vacuum Truck. Environmental agency will be contacted for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

|                                      |   |                             |                                   |
|--------------------------------------|---|-----------------------------|-----------------------------------|
| Signature: <i>Dana DeLaRosa</i>      | OIL CONSERVATION DIVISION                                 |                             |                                   |
| Printed Name: Dana DeLaRosa          | Approved by Environmental Specialist: <i>Kellie Jones</i> |                             |                                   |
| Title: Field Admin Support           | Approval Date: 01/26/2016                                 | Expiration Date: 03/26/2016 |                                   |
| E-mail Address: dana.delarosa@dv.com | Conditions of Approval:                                   |                             | Attached <input type="checkbox"/> |
| Date: 1/25/2016 Phone: 575.746.5594  |   |                             | IRP-4116                          |

\* Attach Additional Sheets If Necessary

nKJ1602628821  
pKJ1602629001




Gaucha Unit 6  
30 BBLs PW 1.22.16



This map is for illustrative purposes only and is neither a legally recorded map nor survey and is not intended to be used as one. The user makes no warranty, representation or agreement of any kind regarding this map.

WGS\_1984\_Web\_Mercator\_Auxiliary\_Sphere  
Prepared by: Dana DeLaRosa  
Map is current as of: 25-Jan-2016



GoogleWMSRoadmap

517, 229, 34E

30 BBLs PW

















