

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	Federal 27 #2 Battery	Facility Type	Gathering
Surface Owner	BLM	Mineral Owner	API No. 30-025-33652

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	27	22S	32E					Lea

Latitude N 32.35745° Longitude W 103.66195°

NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	2 bbls oil, 8 bbls produced water	Volume Recovered	5 bbls
Source of Release	Stress/fatigue of 3" poly flow line	Date and Hour of Occurrence	01/14/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Kellie Jones, Jamie Keyes-NMOCD; Shelly Tucker-BLM		
By Whom?	Kathy Purvis @ BBC International Inc.	Date and Hour	01/14/2016 @ 1:55 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					



RECEIVED

By Kellie Jones at 7:32 am, Jan 27, 2016

Describe Cause of Problem and Remedial Action Taken.*
Stress/fatigue of a 3" poly flow line caused 2 bbls oil and 8 bbls of produced water onto the ground. A vacuum truck recovered 5 bbls of fluids and the line was repaired/recovered.

Describe Area Affected and Cleanup Action Taken.*
The affected area is approximately 30' x 50' and 2' x 100'. Remediation will be completed in accordance with an approved remediation plan from NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:			
Printed Name:	Casey Summers	Approved by Environmental Specialist: 	
Title:	NM Environmental Advisor	Approval Date:	01/27/2016
		Expiration Date:	03/27/2016
E-mail Address:	Casey.Summers@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date:	1/26/16	Site samples required. Delineate and remediate as per MNOCD guides. Geotag photographs of remediation recommended.	1RP-4119
Phone:	(575) 513-8289		

* Attach Additional Sheets If Necessary

nKJ1602727260
pKJ1602727373