

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 10:19 am, Feb 15, 2016

Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Key Energy Services	Contact Bobby Sisson
Address 1301 McKinney St. Ste 1800. Houston TX 77010	Telephone No. 806-401-4349
Facility Name Christmas SWD	Facility Type Clas II Injection well - SWD

Surface Owner Millard Deck Testamentary Trust	Mineral Owner Millard Deck Testamentary	API No. 30-025-10500
---	---	----------------------

LOCATION OF RELEASE

Unit Letter B	Section 28	Township 22S	Range 37E	Feet from the 330	North/South Line N	Feet from the 2310	East/West Line E	County Lea
------------------	---------------	-----------------	--------------	----------------------	-----------------------	-----------------------	---------------------	---------------

Latitude 32.44234 Longitude -103.177

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 100 BBLS	Volume Recovered BBLS
Source of Release Gunbarrel Tank	Date and Hour of Occurrence 02/01/16 8:15 am	Date and Hour of Discovery 02/01/16 8:15 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kellie Jones	
By Whom? Maren Coligan	Date and Hour 02/01/2016 9:25am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Gunbarrel tank running over. The water leg clogged up and over running the gunbarrel tank. The gunbarrel tank is being shut down and prepared to be cleaned out.

Describe Area Affected and Cleanup Action Taken.*

The spill was 100% contained inside the berm and the containment is lined. The spill was picked up immediately.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Bobby Sisson	Approved by District Supervisor: 	
Title: Area Director	Approval Date: 02/15/2016	Expiration Date: 04/15/2016
E-mail Address: bsisson@keyenergy.com	Conditions of Approval:	Attached <input type="checkbox"/> IRP 4180
Date:	Phone: 806 -401-4349	

* Attach Additional Sheets If Necessary

nJXK1604637004
pJXK1604637116