

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 12:45 pm, Feb 15, 2016

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: CORAZON 4 STATE SWD #1	Facility Type: Battery

Surface Owner:	Mineral Owner: State	API No. 30-025-40944
----------------	----------------------	----------------------

LOCATION OF RELEASE

Unit Letter J	Section 4	Township 21S	Range 33E	Feet from the 3800'	North/South Line North	Feet from the 2500'	East/West Line East	County Lea
------------------	--------------	-----------------	--------------	------------------------	---------------------------	------------------------	------------------------	---------------

Latitude 32.5118523 Longitude -103.577034

NATURE OF RELEASE

Type of Release: Oil & Produced Water	Volume of Release: 2 bbls Oil & 17 bbls PW	Volume Recovered: 0 bbls Oil & 17 bbls PW
Source of Release: Tank overflow	Date and Hour of Occurrence: 1-23-2016 7:50 am	Date and Hour of Discovery: 1-23-2016 7:50 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

This release was caused by an alarm failure. Vacuum trucks and a pressure washer were dispatched to recover all standing fluid.

Describe Area Affected and Cleanup Action Taken.*

This release occurred within polyurea containment. After repairs were made the facility was cleaned and placed back into service.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Robert McNeill		Approved by Environmental Specialist: 	
Title: Environmental Manager		Approval Date: 02/15/2016	Expiration Date: ///
E-mail Address: rmcneill@concho.com		Conditions of Approval:	
Date: February 6, 2016 Phone: 432-230-0077		Attached <input type="checkbox"/> IRP 4181	

* Attach Additional Sheets If Necessary

nJXK1604645791

pJXK1604645887