

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 7:07 am, Feb 17, 2016

Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: ConocoPhillips	Contact: Jose A Zepeda	
Address: 1410 N West County Road	Telephone No. 575-391-3165	
Facility Name: SEMU Eumont #84	Facility Type: Well	
Surface Owner: State	Mineral Owner: N/A	API No. 3002520654

LOCATION OF RELEASE

Unit Letter A	Section 22	Township 20S	Range 37E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
-------------------------	----------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	----------------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release: Produce Water	Volume of Release: 5.4	Volume Recovered: 0
Source of Release: transite pipe	Date and Hour of Occurrence 02/13/16 0800	Date and Hour of Discovery SAME
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jamie Keyes	
By Whom? Jose A Zepeda	Date and Hour: 02/16/2017 1520 hrs	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	


If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.* On February 13, 2016 at 0800 MST at SEMU Eumont 84, a leak occurred when a third party crossed over a 8 inch transite pipe during the backfill process resulting in a release of 5.4 bbls of produced water with none recovered. Immediate action was to shut down job and isolate the line. Spill site will be remediated in according to NMOCD guidelines.

Describe Area Affected and Cleanup Action Taken.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: JOSE A ZEPEDA		OIL CONSERVATION DIVISION	
Printed Name: Jose A Zepeda		Approved by Environmental Specialist: 	
Title: LEAD HSE	Approval Date: 02/17/2016	Expiration Date: 04/17/2016	
E-mail Address: Jose. A. Zepeda@conocophillips.com	Conditions of Approval: Discrete site samples only. Delineate and remediate per NMOCD guidelines.		Attached <input type="checkbox"/> 1RP 4183
Date: 02/16/16	Phone: 575-391-3158		

* Attach Additional Sheets If Necessary

nJXK1604825469
pJXK1604825576