

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 9:30 am, Feb 29, 2016

Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077	
Facility Name: ALBATROSS STATE COM #002H	Facility Type: Battery	
Surface Owner:	Mineral Owner: State	API No. 30-025-41544

LOCATION OF RELEASE

Unit Letter B	Section 30	Township 18S	Range 35E	Feet from the 190'	North/South Line North	Feet from the 1980'	East/West Line East	County Lea
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	------------------------	------------------------	---------------

Latitude 32.725502 Longitude -103.4947205

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 20 bbls	Volume Recovered: 5 bbls
Source of Release: Gasket	Date and Hour of Occurrence: 2/9/2016 11:00 am	Date and Hour of Discovery: 2/9/2016 11:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

This release was caused when a gasket on failed on a FWKO. Vacuum trucks were dispatched to recover the standing fluid.

Describe Area Affected and Cleanup Action Taken.*

The release occurred within a lined containment. A spray of oil misted over the pad and nearby pasture. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Robert Grubbs		Approved by Environmental Specialist: 	
Title: Senior Environmental Coordinator		Approval Date: 02/29/2016	Expiration Date: 04/29/2016
E-mail Address: rgrubbs@concho.com		Conditions of Approval: Discrete site samples only. Delineate and remediate per NMOCD guidelines.	
Date: February 23, 2016		Attached <input type="checkbox"/> IRP 4194	
Phone: 432-230-0077			

* Attach Additional Sheets If Necessary

nJXK1606034056
pJXK1606034142