

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

RECEIVED

By JKeyes at 9:16 am, Apr 04, 2016

Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Release Notification and Corrective Action

Name of Company Oxy USA Inc.		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Address 3145 W. State Rd #114, Levelland, TX 79336		Contact Matthew Ledesma			
Facility Name SHU #193		Telephone No. (806) 894-0210			
		Facility Type Line Break			
Surface Owner Oxy		Mineral Owner		API No. 30-025-28984	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	5	19S	38E					Lea County, NM

Latitude N 32.68450°

Longitude W 103.16242°

NATURE OF RELEASE

Type of Release Oil and produced water	Volume of Release 1 bbl oil, 670 bbls of produced water	Volume Recovered 670 bbls fluids
Source of Release 3" Fiberglass injection line hit by 3 rd party construction crew	Date and Hour of Occurrence 03/08/2016	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jamie Keyes-NMOCD	
By Whom? Jimmy King @ Oxy	Date and Hour 03/18/2016 @ 8:02 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A 3rd party construction crew struck an injection line causing 1 bbl of oil and 670 bbls of produced water to spill. A vacuum truck recovered 670 bbls of fluids and the line was repaired.

Describe Area Affected and Cleanup Action Taken.*

The area affected is approximately 60' x 3' both on and off location. Remediation will be completed in accordance with a remediation plan approved by NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:

Printed Name: Matthew Ledesma

Title: HES Ops Specialist

E-mail Address: Matthew.Ledesma@oxy.com

Date: 3/30/16

Phone: (806) 894-0210

OIL CONSERVATION DIVISION

Approved by Environmental Specialist: *Jamie Keyes*

Approval Date: 04/04/2016

Expiration Date: 06/04/2016

Conditions of Approval:

Discrete site samples only. Delineate and remediate per NMOCD guidelines. Photos of remediation recommended.

Attached ☐
1RP 4227

* Attach Additional Sheets If Necessary

nJXK1609533146
pJXK1609533293