

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 8:54 am, Apr 12, 2016

Form C-141

Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	MLMU #247	Facility Type	Well
Surface Owner	Kelly Myers	Mineral Owner	
		API No.	30-025-11044

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	7	24S	37E					Lea County, NM

Latitude N 32.22625° Longitude W 103.19567°

NATURE OF RELEASE

Type of Release	Oil and produced water	Volume of Release	3 bbls oil, 7 bbls produced water	Volume Recovered	0 bbls
Source of Release	Compromised 2" steel production flow line	Date and Hour of Occurrence	04/07/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jamie Keyes-NMOCD		
By Whom?	Kathy Purvis @ BBC International	Date and Hour	04/07/2016 @ 4:07 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

A compromised 2" steel production flow line leaked 3 bbls of oil and 7 bbls of produced water. No fluids were recovered and the line was repaired/replaced.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 12' x 25' both on and off location about 45' west of the wellhead. Remediation will be completed in accordance with a remediation plan approved by NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Casey Summers		Approved by Environmental Specialist: 	
Title: NM Environmental Advisor		Approval Date: 04/12/2016	Expiration Date: 06/12/2016
E-mail Address: Casey_Summers@oxy.com		Conditions of Approval:	
Date: 4-11-16	Phone: (575) 513-8289	Discrete site samples only, delineate and remediate per NMOCD guidelines.	
		Attached <input type="checkbox"/> 1RP 4242	

* Attach Additional Sheets If Necessary

nJXK1610331780
pJXK1610331922