

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS OCD

Form C-141
Revised August 8, 2011

APR 14 2016
Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

XX Initial Report ☐ Final Report

Name of Company	AMERICO ENERGY RESOURCES, LLC	Contact	JIM BROWN
Address	7575 SAN FELIPE, SUITE 200, HOUSTON, TX 77063	Telephone No.	713-984-9700
Facility Name	DENTON STATE "T"	Facility Type	PRODUCTION
Surface Owner	STATE	Mineral Owner	STATE
		API No.	30-025-05233

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	2	15S	37E	990	SOUTH	990	WEST	LEA

Latitude 33.043638 Longitude -103.172892

NATURE OF RELEASE

Type of Release	PRODUCED WATER W/ SKIM OIL	Volume of Release	30 BBLS	Volume Recovered	30 BBLS
Source of Release	WATER TANK OVERFLOW	Date and Hour of Occurrence	UNK	Date and Hour of Discovery	7:21 AM 03-22-2016
Was Immediate Notice Given?	<input type="checkbox"/> Yes XX No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes XX No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

WATER TANK OVERFLOWED DUE TO MALFUNCTIONING DUMP VALVE. TRANSFER PUMP FAILED. REBUILT DUMP AND CONTROLLER. REPAIRED TRANSFER PUMP.

Describe Area Affected and Cleanup Action Taken.*

VACUUM TRUCK PULLED 30 BBLS FLUID OUT OF FIREWALL. CURRENTLY WRITING PROCEDURE AND COSTS TO REMEDIATE ENTIRE PRODUCTION BATTERY AS PER JAMIE KEYES' INSPECTION AND RECOMMENDATIONS. 2 CONTRATORS HAVE REVIEWED LOCATION AT THIS TIME.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: JAMES G. BROWN		Approved by Environmental Specialist: 	
Title: OPERATIONS MANAGER		Approval Date: 04/14/2016	Expiration Date: 06/14/2016
E-mail Address: jim.brown@americoenergy.com		Conditions of Approval:	
Date: 04/13/16 Phone: 713-984-9700		Discrete site samples only. Delineate and remediate per NMOCD guidelines.	
		Attached <input type="checkbox"/> 1RP 4246	

* Attach Additional Sheets If Necessary

nJXK1610545915
pJXK1610545999