

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

**HOBBS OCD**  
**APR 18 2016**  
**RECEIVED**

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Echo Production, Inc.	Contact: Buck Dollar
Address: 616 Fifth Street Graham, Texas	Telephone No.: (940) 549-3292
Facility Name: E. Livingston Ridge; Delaware	Facility Type: Steel Pipeline

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-025-36656
------------------------	------------------------	----------------------

#### LOCATION OF RELEASE

Unit Letter K, M, & N	Section 31	Township 22 S	Range 32E	Feet from the 1810"	North/South Line South	Feet from the 330"	East/West Line East	County Lea
--------------------------	---------------	------------------	--------------	------------------------	---------------------------	-----------------------	------------------------	---------------

Latitude 32.342537 Longitude -103.720823

#### NATURE OF RELEASE

Type of Release Crude Oil & Produced	Volume of Release: unknown	Volume Recovered: unknown
Source of Release: 2-7/8 steel line	Date and Hour of Occurrence: unknown	Date and Hour of Discovery: 2/17/2016, 15:00
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

During a relinquishment inspection, Randal Pair, BLM-Carlsbad EPS and Fernando Banos, EPS, discovered three leaks/spills sites. During a site visit with Jamie Keyes, NMOCD ES, District 1, discovery of the fourth site. GPS coordinates of all four are 32.34580 -103.718976, 32.343859 -103.717914, 32.344818 -103.716257, and 32.345785 -103.714121.

Describe Area Affected and Cleanup Action Taken.

The releases impacted approximately 16,662sq. ft. of pasture along the ROW. The affected area will be remediated in accordance with NMOCD and BLM guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>W.D. Dollan</u>		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Buck Dollan		Approved by Environmental Specialist: <u>Jamie Keyes</u>	
Title: Echo Production, Inc.		Approval Date: <u>04/18/2016</u>	Expiration Date: <u>06/18/2016</u>
E-mail Address: buck@echoproduction.com		Conditions of Approval:	
Date: <u>4-12-16</u> Phone: (940) 549-3292		Discrete samples only. Delineate and remediate per NMOCD guidelines. Ensure BLM concurrence/approval	
		Attached <input type="checkbox"/> IRP 4250	

\* Attach Additional Sheets If Necessary

nJXK1610932972  
pJXK1610933098